



Service Bulletin

SB 04-24

SUBJECT: WS 1 Option – Low Coolant Level Sensor

We have been made aware that the existing low coolant level sensors can leak coolant in some cases. We have now introduced a new enhanced sensor on all production units from 1 December 2004. The part number changes are as follows:

Description	Old Part Number	New Part Number
Low Water Level Switch	622-286	917-452
Low Water Level Probe ¼ " NPTF	622-374	917-453
Low Water Level Probe ½ " NPTF	622-375	917-454

The old part numbers will no longer be available as spare parts. The old part number is superseded with the new part number. Any old part numbers in dealer stock may be returned to the Newberry parts facility for refund (call 803-321-1100 ext 45 for a return authorization).

Low coolant level sensor failures that occur within the genset warranty period will be covered under normal warranty terms and conditions. Failures outside warranty are on a chargeable basis to the customer.