

Olympian Service Bulletin



SB 06 – 01 (622-333)

16 January 2006

SUBJECT: Part number 622-333 oil pressure sender / switch.

PROBLEM:

It has been determined that a high percentage of part number 622-333 (oil pressure sender / switch) are failing in the field resulting in a false oil pressure reading on the pressure gauge.

Failures occur as a result of long term wear to an internal wire wound coil that is part of the sender. The oil pressure switch however is not affected and the low oil pressure shutdown remains operable.

SOLUTION:

It is recommended that part number 622-333 (oil sender / switch) should be proactively changed as part of the 1000-hour service interval.

Failures of 622-333 occurring after 1000 hours will not be covered under standard warranty from 1st March 2006.

Paul O'Neill
Service Manager
FG Wilson (Eng) Ltd