



No.: 07 TS - 27  
April 19, 2007

TO: Service Locations

FROM: Technical Service Development

SUBJECT: **DDEC VI Flash Code 2615 SPN 247 FMI 0 - MCM engine hours higher then expected**

## ISSUE

SPN 247 FMI 0 is a code created when the diagnostic software connects to the DDEC VI Motor Control Module (MCM) and Common Powertrain Controller (CPC).

## CAUSE

The code may be set when either Detroit Diesel Diagnostic Link (DDDL) 7.0 or Detroit Diesel Reprogramming Software (DDRS) is connected to a DDEC VI MCM and CPC.

## REQUIRED ACTION

No troubleshooting is necessary. An Amber Warning Lamp (AWL), formerly identified as the Check Engine Lamp (CEL), does not illuminate when this code is set..

If this is the only code found, delete the code.

If multiple codes are found, troubleshoot the other codes using the appropriate manuals and disregard the SPN 247 FMI 0 code.

The SPN 247 FMI 0 code will be corrected in a future CPC software release.

## CONTACT INFORMATION

Please contact the DDC Customer Support Center at 313-592-5800 if you have any questions.