



No.: 07 TS-39
July 21, 2007

TO: DDC Distributors, Global Dealers(On-Highway), G2 Members, OEMS

FROM: Technical Support

SUBJECT: **Diagnostic Induced Fault Codes**

REQUIRED ACTION

In the event any sensor or actuator is disconnected and the ignition is turned ON, a fault code may set (e.g. when the turbo actuator is disconnected from a DDEC VI engine under these conditions, a SPN 2795 FMI 9 Turbo Actuator Communication Error will set). It is not necessary to troubleshoot these self induced faults.

If you suspect a diagnostic induced fault code has occurred, clear the code(s) and see if they reset. If they reset, perform the diagnostic routines related to that code. If they do not reset, no troubleshooting is necessary.

CONTACT INFORMATION

Please contact the Detroit Diesel Customer Support Center at 313-592-5800 if you have any questions.