

# DETROIT DIESEL



## MBE900 Service Information

**NUMBER:** 1-MBE900-05   **S.M. REF.:** 15   **ENGINE:** MBE900   **DATE:** July 2005

**SUBJECT: CRANKCASE PRESSURE CORRECTION AND REVISED TROUBLESHOOTING SECTION**

### INTRODUCTION

The crankcase pressure in the MBE900 Service Manual has been found to be in error and has been corrected. Also, Chapter 15, Troubleshooting Section of the *MBE900 Service Manual* (6SE414) has been revised.

### DETAILS AND REASON

The crankcase pressure specification of 1.50 kPa (6 in. H<sub>2</sub>O) is incorrect in Chapter 15. The correct crankcase pressure should be 0.62 kPa (2.5 in. H<sub>2</sub>O). The attached service manual pages have been updated with the correct specification.

The troubleshooting section, Chapter 15, has been revised to reflect the most current available information along with a revised engine fault code section.

Remove the complete Chapter 15, troubleshooting section from the manual and replace with the attachment pages.

### ADDITIONAL SERVICE INFORMATION

Additional service information is available in the Detroit Diesel *MBE900 Service Manual*, 6SE414. The next revision to this manual will include the revised information. As a convenience to holders of the *MBE900 Service Manual*, information in service manual format is attached. The page(s) may be inserted into the manual.

### NOTE:

Manual insert pages are numbered for insertion into the current *MBE900 Service Manual* dated April 2004. Service manuals are available from authorized Detroit Diesel distributors. If this bulletin was obtained from the Internet, service manual page(s) are available by returning to the screen "SIB Index", selecting attachment pages, and printing the page(s).

---

**DETROIT DIESEL**  
CORPORATION



13400 Outer Drive, West / Detroit, Michigan 48239-4001  
Telephone: 313-592-5000  
[www.detroitdiesel.com](http://www.detroitdiesel.com)

---