
SERVICE BULLETIN

Original Issue Date: **2/97**Model: **20-300 kW**Market: **Industrial**Subject: **Voltage Regulator A-226709 for Reducing Light Flicker**

The new voltage regulator A-226709 is available to reduce some types of nonlinear load abnormalities which cause light flicker. The voltage regulator circuitry improves noise filtering and stabilization. Using the new voltage regulator may reduce or eliminate some harmonic distortion problems.

Harmonic distortion is a load-induced occurrence and is not considered a warrantable generator set problem. The Generator Warranty Department will not accept warranty claims using the new voltage regulator to solve harmonic distortion problems.

Contact the Generator Service Department before purchasing the new voltage regulator for additional information and recommendations.

Order the new voltage regulator A-226709 through the Service Parts Department. The new voltage regulator is a direct replacement for the C-255670 voltage regulator.

Routing	Service Manager	Sales Manager	Parts Manager	Technician No. 1	Technician No. 2	Technician No. 3	Return This to
Initial Here							