


PARTS BULLETIN

Original Issue Date: 7/97

Model: **60-100GS**Market: **Industrial**Subject: **Field Exciter Assembly Correction**

Parts Catalog MP-5614 lists the wrong field exciter assembly part number for some generator set specifications. See Figure 1 for a picture of the field exciter assembly. Choose the correct part number from the chart below. Please make a note of the correction in Parts Catalog MP-5614 4/96, 50-100GS, page 33, item 29.



1. Rotor Assembly
2. Field Exciter Assembly
3. End Bracket

Figure 1. Alternator Components

Generator Set Specification	Field Exciter Part Number
60GS	
193040	276657
193043	276657
70GS	
193045	276657
193046	276657
193047	276657
193048	276657
193049	276657
193050	276657
80GS	
193051	276657
193052	276657
193053	276657
193054	276657
193055	276657
193056	276657
100GS	
193057	276657
193058	276657
193059	276657
193060	276657
193061	276657
193062	276657

Routing	Service Manager	Sales Manager	Parts Manager	Technician No. 1	Technician No. 2	Technician No. 3	Return This to
Initial Here							