

January 26, 2001

Re: Olympian XQ Rental Gen-Set Enhancements

A number of product enhancements for Olympian XQ gen-sets have been identified and introduced into our production system in recent months. These include:

- an adjustment to the governors to prevent the possibility of overspeed upon start-up.
- a change in the control panel wiring to stop the monitoring functions and consequent battery drainage when the gen-set control switch is in the "OFF" position.
- the extension of the fuel tank breather pipe to eliminate fuel spillage during transit.

We realize some of these modifications may be desirable for Olympian XQ gen-sets already in the field and would like to advise:

- any Olympian XQ gen-sets up to serial number *F7319A/001* which go into overspeed upon start up should be modified as per the attached procedure. We will free issue to dealers the parts described on the attached procedure and reimburse up to two hours labor for this modification on the XQ30P2 and up to one hour labor on the XQ60P2, XQ75P2 and XQ105P2. Claims for the labor should be submitted on the warranty system with reference to program *SB01-01* in the claim story.
- to eliminate battery drainage (and monitoring functions) when the Olympian XQ gen-set control switch is in the "OFF" position follow the attached procedure. We will free issue the parts described on the attached procedure and will reimburse dealers up to one hour for this modification. Claims for the labor should be submitted under the warranty system with reference to program *SB01-02* in the claim story.
- on request, extended breather pipes will be free issued for any Olympian XQ gen-set up to serial number *F4497A/001*.

To obtain free issue parts as described above please send an email note or fax to Kathy Goff at goffke@fgwilson.com or (803) 321-9128, respectively, listing the models, specific serial numbers and the shipping address.

The modifications described above need be done only once; we will accept one claim per serial number for each modification. We would recommend the changes described above are performed at the dealer's premises and will not reimburse for travel time.

We believe these changes will enhance the value of the Olympian XQ gen-set offering.

Attachments:

- XQ30P2 Electronic Governor Procedure
- XQ60-105P2 Electronic Governor Procedure
- XQ Battery Drainage Modification Procedure