

2213389

Kahler Beige

2665

2653

2627

MATERIAL SAFETY DATA SHEET

F78H1956-4370
01 00MANUFACTURER'S NAME
THE SHERWIN-WILLIAMS COMPANY
101 Prospect Avenue N.W.
Cleveland, OH 44115EMERGENCY TELEPHONE NO.
(216) 566-2917DATE OF PREPARATION
01-NOV-94INFORMATION TELEPHONE NO.
(216) 566-2902

Section I -- PRODUCT IDENTIFICATION

PRODUCT NUMBER

F78H1956-4370

HMIS CODES

Health	2
Flammability	4
Reactivity	0

PRODUCT NAME

F78H1957-4370 filled into OMNI-PAK* LAV aerosol, K.C. Beige

PRODUCT CLASS

Aerosol Coating

Section II -- HAZARDOUS INGREDIENTS

INGREDIENT CAS No.	% by WT	ACGIH TLV	OSHA PEL	UNITS	V.P.
Propane 74-98-6	15		1000	PPM	760.00
Toluene. 108-88-3	5 STEL	50	100 150	PPM (Skin) PPM (Skin)	22.00
Ethylbenzene 100-41-4	1 STEL	100 125	100 125	PPM PPM	7.10
Xylene. 1330-20-7	7 STEL	100 150	100 150	PPM PPM	5.90
Acetone. 67-64-1	49 STEL	750 1000	750 1000	PPM PPM	180.00
Ethyl 3-Ethoxypropionate. 763-69-9	4	Not Established			1.11
Titanium Dioxide. 13463-67-7	8	10	10(5)	MG/M3 as Dust ***	

*** Total Dust (Respirable Fraction)

Section III -- PHYSICAL DATA

PRODUCT WEIGHT -- 6.78 lb./gal. EVAPORATION RATE -- Faster than Ether
 SPECIFIC GRAVITY -- 0.82 VAPOR DENSITY -- Heavier than Air
 BOILING POINT -- 10 -342 F MELTING POINT -- N.A.
 VOLATILE VOLUME -- 92 % SOLUBILITY IN WATER -- N.A.
 VOLATILE WEIGHT -- 82.58 % (less Federally Exempt Solvents)
 HMIS -- 2 4 0

Section IV -- FIRE AND EXPLOSION HAZARD DATA

FLASH POINT LEL UEL
 Propellant (0 F 1.0 12.8
 EXTINGUISHING MEDIA
 Carbon Dioxide, Dry Chemical, Foam

12 OZ AEROSOL

131900

F78H1956-4370

page 3

=====

INCOMPATIBILITY

None known.

HAZARDOUS DECOMPOSITION PRODUCTS

By fire: Carbon Dioxide, Carbon Monoxide

HAZARDOUS POLYMERIZATION

Will not occur

=====

Section VII -- SPILL OR LEAK PROCEDURES

=====

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED

Remove all sources of ignition. Ventilate and remove with inert absorbent.

WASTE DISPOSAL METHOD

Waste from this product may be hazardous as defined under the Resource Conservation and Recovery Act (RCRA) 40 CFR 261.

Waste must be tested for ignitability to determine the applicable EPA hazardous waste numbers.

Do not incinerate. Depressurize container. Dispose of in accordance with Federal, State, and Local regulations regarding pollution.

=====

Section VIII -- PROTECTION INFORMATION

=====

PRECAUTIONS TO BE TAKEN IN USE

Use only with adequate ventilation. Avoid breathing vapor and spray mist. Avoid contact with skin and eyes. Wash hands after using.

This coating may contain materials classified as nuisance particulates (listed "as Dust" in Section II) which may be present at hazardous levels only during sanding or abrading of the dried film. If no specific dusts are listed in Section II, the applicable limits for nuisance dusts are ACGIH TLV 10 mg./m³ (total dust), OSHA PEL 15 mg./m³ (total dust), 5 mg./m³ (respirable fraction).

VENTILATION

Local exhaust preferable. General exhaust acceptable if the exposure to materials in Section II is maintained below applicable exposure limits. Refer to OSHA Standards 1910.94, 1910.107, 1910.108.

RESPIRATORY PROTECTION

If personal exposure cannot be controlled below applicable limits by ventilation, wear a properly fitted organic vapor/particulate respirator approved by NIOSH/MSHA for protection against materials in Section II.

When sanding or abrading the dried film, wear a dust/mist respirator approved by NIOSH/MSHA for dust which may be generated from this product, underlying paint, or the abrasive.

PROTECTIVE GLOVES

None required for normal application of aerosol products where minimal skin contact is expected. For long or repeated contact, wear chemical resistant gloves.

EYE PROTECTION

Wear safety spectacles with unperforated sideshields.

=====

Section IX -- PRECAUTIONS

=====

DOL STORAGE CATEGORY

1A