

Lesson 8

OTPC Options

Installing Options



Download Proper Calibration

Battery Disconnected

Static Wrist Strap

Install Option and Wiring Harness

Battery Connected

Both sources of power disconnected

Test transfer switch

OTPC Options



Digital Display (Level 1 Control)

LED Bargraph & Load Module (Level 2 Control)



Relay Module (Level 1 & 2 Controls)

Load Shed (Level 1 & 2 Controls)

Network Module (Level 1 & 2 Controls)


Auxiliary Relays (Level 1 & 2 Controls)

Digital Display Option





Alignment Pin Notches

Metering Package Option




Level 2 Digital Board
and LED Bargraph

Current Module




Shorting Block




Current
Transformers


Relay Module Option



Load Shed Option




OH 8-6




S&TT 10/02

PowerCommand[®] Network Option



Auxiliary Relays



8-1 OTPC Options Quiz