



Find program and open




Click on refresh list when cable is connected from 2020 to computer.



Highlight com port and click on box update selected.

Follow the prompts until done



If you get a checksum failure press the reset button ( below the right arrow key) to clear.