



NOTES:

- 1- INSTALL 2000 OHM - 1/2 WATT POTENTIOMETER IN SERIES WITH VAR TERMINALS 6 AND 7 IF A REMOTE VOLTAGE CONTROL IS REQUIRED
- 2- USE JUMPER WIRE PROVIDED FOR 50Hz OR 60Hz OPERATION

				<input checked="" type="checkbox"/> MAX. SURFACE ROUGHNESS UNLESS NOTED OTHERWISE TOL. ON XX± XXX±.005 XXXX±.0005 ANGLES±	
				DRAWN BY DRS 05-22-2000 CHKO BY TM 05-22-2000 APPD BY WBD 05-22-2000	
1 05-22-2000 NEW DRAWING GM53454		DRS		PART NAME CONNECTION DIAGRAM PM300 - 240 DELTA - 12 LEAD	
REV	DATE	CHANGE	NAME	DRWG NO	

