



No.: 08 TL-15
August 11, 2008

TO: Service Locations

FROM: Technical Support Development

SUBJECT: **W470589054000 Camshaft Timing Tool Replacing W470589024000**
(Old Tool Number)

ISSUE

An updated Camshaft timing tool W4705890**5**4000 (red in color) has been sent to your facility to replace original tool number W4705890**2**4000 (black in color). The tool may arrive at your location with the original tool number W470589024000 located on the outside of the packaging, although a new Camshaft timing tool is inside the package. In the near future, the packaging will also be updated to show the replacement tool number. Please refer to Tool Letter [08 TL-13](#) for instructions on replacing the old tool (W4705890**2**4000) with the new tool (W4705890**5**4000).

CONTACT INFORMATION

Please call the Detroit Diesel Customer Support Center at 313-592-5800 or email csc@detroitdiesel.com and ask for the Technical Support Department to answer any questions regarding this tool or procurement of this tool.