

DETROIT DIESEL



MBE900 Service Information

NUMBER: 07-MBE900-04 **S.M. REF.:** 2.3 **ENGINE:** MBE 900 **DATE:** November 2004

SUBJECT: SERVICE MANUAL CORRECTIONS

INTRODUCTION

The MBE 900 Service Manual has been found to be in error and has been corrected. The correct tool number for the heat isolator installer is J 46393.

DETAILS AND REASON

This SIB impacts Chapter 2, "Fuel System," and the attachment pages should be inserted in section 2.3, "Nozzle Holder."

Remove pages 2-15 thru 2-18 and replace with the same number of corrected pages.

ADDITIONAL SERVICE INFORMATION

Additional service information is available in the Detroit Diesel *MBE 900 Service Manual*, 6SE414. The next revision to this manual will include the revised information. As a convenience to holders of the *MBE 900 Service Manual*, information in service manual format is attached. The page(s) may be inserted into the manual.

NOTE:

Manual insert pages are numbered for insertion into the current *MBE 900 Service Manual* dated April 2004.

DETROIT DIESEL
CORPORATION



13400 Outer Drive, West / Detroit, Michigan 48239-4001
Telephone: 313-592-5000
www.detroitdiesel.com
