



Circular No. 40-04/D19

Friedrichshafen, 14. December 2004
sid-mü

Distribution: Off-Highway Sales Organization (Region 3 only)

Series 2000 Genset Engines Changed connection point for coolant venting

The connection point for engine coolant venting on Series 2000 genset engines has been changed (see drawing on next page).

The previous engine-side line between the elbow with the connection point "Inlet pre-heating line" and the previous connection point is no longer fitted. In future, the venting line must be connected directly at the connecting elbow. Connection geometry remains unaltered.

For engines with air-charge-air cooling a suitable hose line is supplied. It must be ensured that the hose line is installed with a continuous upward incline.

The amended engine installation drawings can be accessed on the Extranet at: Home / Sales Support / Power Generation / Diesel Engines / Series 2000.

...


DaimlerChrysler Off-Highway

MTU Friedrichshafen GmbH
88040 Friedrichshafen
Germany
info@mtu-online.com
www.mtu-online.com

Detroit Diesel Corporation
13400 Outer Drive
Detroit, Michigan 48239-4001, USA
info@detroitdiesel.com
www.detroitdiesel.com



- 2 -



Knut Müller

Frank Forberger

This circular is also available on the MTU Extranet at: Sales Support/Circulars

DaimlerChrysler Off-Highway

MTU Friedrichshafen GmbH
88040 Friedrichshafen
Germany
info@mtu-online.com
www.mtu-online.com

Detroit Diesel Corporation
13400 Outer Drive
Detroit, Michigan 48239-4001, USA
info@detroitdiesel.com
www.detroitdiesel.com