


PARTS BULLETIN

Original Issue Date: **10/99**
 Model: **80-100DS/DSE, 150/180DS**
 Market: **Industrial**
 Subject: **Field Exciter Assembly Correction**

Parts Catalog MP-5681 lists the wrong field exciter assembly part number for some generator set specifications. See Figure 1 for an illustration of the field exciter assembly. Choose the correct part number from the chart. Please make a note of the correction in Parts Catalog MP-5681 6/99, 20-180DS/ESE, page 27, item 28.



1. Rotor Assembly
2. Field Exciter Assembly
3. End Bracket

Figure 1. Alternator Components

Generator Set Specification	Field Exciter Part Number
80DS/DSE	
192501	276657
192502	276657
192503	276657
192504	276657
192505	276657
192506	276657
192519	276657
192520	276657
192521	276657
192522	276657
192523	276657
192524	276657
100DS/DSE	
192601	276657
192602	276657
192603	276657
192604	276657
192605	276657
192606	276657
192619	276657
192620	276657
192621	276657
192622	276657
192623	276657
192624	276657
150DS	
192803	257963
192806	257963
180DS	
192901	257963
192902	257963
192903	257963
192904	257963
192905	257963
192906	257963

Routing	Service Manager	Sales Manager	Parts Manager	Technician No. 1	Technician No. 2	Technician No. 3	Return This to
Initial Here							