



NOTES:

- 1- INSTALL 2000 OHM - 1/2 WATT POTENTIOMETER IN SERIES WITH VAR TERMINALS 6 AND 7 IF A REMOTE VOLTAGE CONTROL IS REQUIRED
- 2- USE JUMPER WIRE PROVIDED FOR 50Hz OR 60Hz OPERATION

				<input checked="" type="checkbox"/> MAX. SURFACE ROUGHNESS UNLESS NOTED OTHERWISE MATL SPEC		UNLESS OTHERWISE SPECIFIED DIMENSIONS ARE IN INCHES TOL. ON XX± XXX±.005 XXXX±.0005 ANGLES±	
				FINISH		WAUSAU, WISCONSIN 54401	
1		01-05-2000	NEW DRAWING	GM 50119	TM	PART NAME CONNECTION DIAGRAM PM300	
REV	DATE	CHANGE			NAME	DRWG NO B-14000-1146	
		SHOP BOOK	PURCHASED	DISTRIBUTION - <del>X</del> - <del>X</del> - <del>X</del> - LM	CADD FILE NO.	14x1146	

DRAWN BY	TM	01-05-2000
CHKD BY	ML	01-05-2000
APPD BY	LM	02-05-2000