

[Previous Screen](#)

◀ Product: NO EQUIPMENT SELECTED
Model: NO EQUIPMENT SELECTED
Configuration: NO EQUIPMENT SELECTED

Troubleshooting

EMCP 3

Media Number -REN7902-01

Publication Date -01/01/2006

Date Updated -27/01/2006

i02461494

Generator Output Sensing Circuit Fault

SMCS - 4490

System Operation Description:

If the engine is running and the EMCP 3 is receiving AC voltage and current information, but not processing any AC measurements, then the "GENERATOR OUTPUT SENSING CIRCUIT FAULT" is made active. The EMCP 3 has failed.

Test Step 1.

Perform the following procedure: Electronic Control Module (Generator Set) - Replace

Results:

- OK - STOP