



TO: Service Locations

FROM: Technical Support Development

SUBJECT: **J-48837 DD15 Injector O-Ring Installer Replacement**

ISSUE

Service locations that ordered DD15 tools on the website received tool J-48837 in the DD15 support tool kit (see Figure 1). Tool J-48837-2 in this kit has been replaced by J-48837-2A. The injector diameter changed causing this tool to have an inner diameter that was too small, requiring a new tool to be made. When you receive the new tool, please remove J-48837-2 and discard it. Replace the old tool with J-48837-2A. The replacement tool will come with updated decals for the storage case and detailed instructions. Tool J-48837-2A will be sent to you at no charge from SPX.




Figure 1. J-48837 – Injector O-ring Installer

CONTACT INFORMATION

Please contact the Detroit Diesel Customer Support Center at 313-592-5800 or email csc@detroitdiesel.com if you have any questions.