

No.: 05 TS-12Rev
February 10, 2006

TO: DDC Distributors, FLLC Dealers

FROM: Technical Service

SUBJECT: **MBE4000 Fuel Filter Application Update**

ISSUE

Standardization of fuel filters for service

REQUIRED ACTION

MBE has standardized on a single service part number for the fuel filter on all MBE4000 engines.

REQUIRED MATERIAL

For all MBE4000 engines, use fuel filter service P/N: 5410900151.

REPAIR PROCEDURE

Reference the *MBE4000 Service Manual* (6SE412) and the *MBE4000 Operators Guide* (6SE411) for proper procedures on replacing the fuel filter. Also reference Technical Service letter 05TS-22.

ADDITIONAL INFORMATION

The new fuel filter replaced former fuel filter P/N: 4570900051 on current production MBE4000 EGR engines and became effective with engine serial number 0460837675 built on November 25, 2005.

CONTACT INFORMATION

Please contact the DDC Customer Support Center at 313-592-5800 if you have any questions.