

DETROIT DIESEL



MBE4000 Service Information

NUMBER: 13-MBE4000-04 **S.M. REF.:** 2A **ENGINE:** MBE 4000 **DATE:** September 2004

SUBJECT: UNIT OF MEASUREMENT CORRECTION

INTRODUCTION

The following information corrects some unit of measurement errors in two tables of Section 2.A, “Additional Information” section of the Fuel System chapter.

DETAILS AND REASON

This SIB impacts Chapter Two, “Fuel System,” and the attachment pages should be inserted in 2.A, the “Additional Information” section of that Chapter.

Remove pages 2-59 and 2-60 and replace with the same number of corrected pages.

ADDITIONAL SERVICE INFORMATION

Additional service information is available in the Detroit Diesel *MBE 4000 Service Manual*, 6SE412. The next revision to this manual will include the revised information. As a convenience to holders of the *MBE 4000 Service Manual*, information in service manual format is attached. The page(s) may be inserted into the manual.

NOTE:

Manual insert pages are numbered for insertion into the current *MBE 4000 Service Manual* dated March 2004. Service manuals are available from authorized Detroit Diesel distributors. If this bulletin was obtained from the Internet, service manual page(s) are available by returning to the screen “SIB Index”, selecting attachment pages, and printing the page(s).

DETROIT DIESEL
CORPORATION



13400 Outer Drive, West / Detroit, Michigan 48239-4001
Telephone: 313-592-5000
www.detroitdiesel.com
