


# DETROIT DIESEL

---



## MBE900 Service Information

**NUMBER:** 2-MBE900-04   **S.M. REF.:** 4.8   **ENGINE:** MBE 900   **DATE:** March 2004

**SUBJECT:** LUBRICATION SYSTEM

### INTRODUCTION

This SIB impacts Chapter 4 and should be added to the *MBE900 Service Manual (6SE414)*.

### DETAILS AND REASON

The new sections support the removal and replacement of various EGR components for the 2004 engine models. Also included is a revised Table of Contents for Chapter 4.

### ADDITIONAL SERVICE INFORMATION

Additional service information is available in the Detroit Diesel *MBE 900 Service Manual, 6SE414*. The next revision to this manual will include the revised information. As a convenience to holders of the *MBE 900 Service Manual*, information in service manual format is attached. The page(s) may be inserted into the manual.

### NOTE:

Manual insert pages are numbered for insertion into the current *MBE 900 Service Manual* dated March 2003. Service manuals are available from authorized Detroit Diesel distributors. If this bulletin was obtained from the Internet, service manual page(s) are available by returning to the screen "SIB Index", selecting attachment pages, and printing the page(s).

---

**DETROIT DIESEL**  
CORPORATION



13400 Outer Drive, West / Detroit, Michigan 48239-4001  
Telephone: 313-592-5000  
[www.detroitdiesel.com](http://www.detroitdiesel.com)